



FORD OTOSAN

FORD OTOSAN

16150

RADIATOR UPPER HOSE



MODEL	MOTOR	YIL
TAUNUS	1.6	1970 / 1994
P100 I	1.6	1982 / 1987

OEM NO : 1517422, 1626285, 6047086, 6047087, 6142187

16151

RADIATOR LOWER HOSE



MODEL	MOTOR	YIL
P100 I	1.6	1982 / 1987
TAUNUS	1.6	1970 / 1994

OEM NO : 554664, 1626290, 6096159, 6096160, 72GB8286BB

16624

VACUUM HOSE



MODEL	MOTOR	YIL
P100 II	1.8 TD	1987 / 1992

OEM NO : 93FF2B047BB, 7048101