



SUBARU
SUBARU



11150

RADIATOR UPPER HOSE



MODEL	MOTOR	YIL
LEGACY II	2.0 i	1994 / 1999
LEGACY II	2.0 i	1994 / 1999
LEGACY I	2.0 GL	1991 / 1993
LEGACY I	2.2	1989 / 1994
LEGACY I	2.0	1991 / 1994

OEM NO : 45167AA020, X4511AA000

11151

RADIATOR LOWER HOSE



MODEL	MOTOR	YIL
LEGACY II	2.5 i	1996 / 1999
LEGACY II	2.0 i	1994 / 1999
LEGACY I	2.0 GL	1991 / 1993
LEGACY I	2.0	1991 / 1993
IMPREZA	2.0 WRX	2000 / 2006

OEM NO : 45167AA030

11200

RADIATOR UPPER HOSE



MODEL	MOTOR	YIL
JUSTY I	1.2	1986 / 1996
JUSTY I	1.2	1986 / 1994

OEM NO : 745162291

11201

RADIATOR LOWER HOSE



MODEL	MOTOR	YIL
JUSTY I	1.0	1984 / 1994
JUSTY I	1.0	1984 / 1995

OEM NO : 745162310

11202

HEATER HOSE



MODEL	MOTOR	YIL
JUSTY I	1.0	1987 / 1994
JUSTY I	1.0	1987 / 1995

OEM NO : 772006422

11250

HEATER HOSE



MODEL	MOTOR	YIL
IMPREZA		

11300

RADIATOR UPPER HOSE



MODEL	MOTOR	YIL
IMPREZA	2.0 i R	2005 / 2007

OEM NO : 45161FE050

60600

TURBO HOSE



MODEL	MOTOR	YIL
OUTBACK IV	2.0 D	2009
OUTBACK III	2.0 D	2008 / 2009
OUTBACK V	2.0 D	2015
LEGACY IV	2.0 D	2008 / 2009
LEGACY V	2.0 D	2009 / 2014

OEM NO : 21869AA170, 21869AA130